BB&T - Prop Insp with Sketch



File #: OMS-167922

Property Information:

Property Owner: HPS Pharmacy Street: 312 Diamond St City: Sistersville State: WV Zip: 26175 Mobile Year: Mobile Serial #: HUD #:

Job #: BBT4-140729-1708037

Contact: **Linda Hayes** Work Phone: **304-758-2815** mobile phone: Home Phone: Mobile Make/Model: *I* Mobile Length: width:

MANDATORY PHOTO REQUIREMENTS: You must have the proper photos to support what you have checked below. These are protected fields, so you must complete these in order to submit. This does not exclude any additional pictures that are asked of you in the special instructions and/or service procedures. Please read all the requirements of this order each time. These are always subject to change. The more pictures the better.

Full Frontal of the subject property- (to include whole building in picture standing back)

🗹 Both sides of the subject property- (make a reasonable attempt, if you cannot please note reason why.)

Full rear of the subject property- (to include whole building in picture standing back)

1 photo of every interior room of the property

Pictures of any deficiencies noted on the report

Street scenes- take pictures looking down each direction (to the left and to the right) of the street from the front of the subject property.

Pictures showing the adjacent and neighboring properties from in front of the subject property regardless if anything is there.

EACH PICTURE MUST BE CLEAR AND NOT BLURRY-If pictures are submitted in poor condition then you will be required to go back and retake them if necessary. If this occurs, you may not be paid for this order especially if it is owner occupied, and owner is upset that they need to give you access again. Please upload using high resolution.

Inspection Date: 8/5/2014

Property Information (check all that apply)

Subject Property Type:	D Office	Retail	Industrial	Residential	
	Vacant Land	Agricultural	Other		
Neighborhood Maintenance Level:	Excellent	Good Goor	Average		
Neighborhood Growth Stage:	Growing	Stable	Declining	Revitilization	
Neighborhood contains:	ApartmentsResidential	Industrial Vacant Land	Commercial	🗹 Retail	

Neighborhood Occupancy:	Many Lease/Rent signs	Few Lease/Rent	No Lease/RentsignsNo For Sale signs		
	Many For Sale signs				
Topography:	Mostly Level	Sloping			
Corner Lot:	Ves	No No			
Utilities Available:	Electricity Gas	WaterPhone	Sewer		
Subject Property Traffic Level: Subject Unit Description	Heavy Traffic	Moderate Traffic	Low Traffic		
Address and Suite Number	Occ	upied? Occupant Ty	pe and Name (office, retail, etc.)		
312 Diamond Street, Sistersvi	Ye Ye Ye Ye Ye	HPS Pharmac NO NO NO NO NO NO NO NO NO NO	y, Retail		

Subject Improvement Description

Provide a detailed description of the property and it's use. (Please be as detailed as possible) Property includes 38 X 66 Masonry (Concrete Block) 1 story Central Business District building with approximately 80% open retail space (20% storage/bathroom/basement steps), being used as a Pharmacy/Retail establishment. Property includes a 52 X 66 gravel parking corner lot at the corner of Diamond Street and West Virginia State Route 2. The building has an HVAC unit atop a 4 year old rubber roof, has a painted exterior, but does not have a front sign (the sign is located on the left side of the building (visible from the traffic flow on State Route 2). The interior was remodeled in 2009 by owner's family. The building contains a small unfinished basement. The original building on the property was much smaller, as evidenced by the basement area and mixed building materials. In the early 1960s, the building was used as a small grocery store. The building is not sprinkled but does have a fire hydrant right outside the front door of the building. The fire department building is .5 miles away and is volunteer; the owner (husband) states individual fire department volunteers are summoned via pager, not siren.

Describe Projected Property Use: Property is in a retail/commercial area near a theater, The Wells Inn Hotel and Restaurant, specialty retail shops, a large local hardware store, convenience and discount stores, and other mixed commercial properties. The open structure of the interior presents a good use for a specialty retail- one with a below average need for storage area-with easily accessible customer parking. Please note that parking lot is only one in neighborhood that is currently gravel. Describe Renovations Made (if any): Owner and family renovated the building by installing flooring (Pergo), cabinetry, a customer service counter, retail racks, two sinks, new front windows, a customer service type drive through window (no square footage extension), front interior accent lighting, and new side windows nearer the ceiling, and divided storage rooms with drywall in the back portion of the building. The owner's family also remodeled and expanded on a small two fixture bathroom (sink and toilet) to include new plumbing, electric baseboard, flooring and paint. The owner and family also did some rewiring, as evidenced in the basement access area and basement.

Estimated Year Built:	Estimated Year Renovated:
1920	2009

Total Number of Units: 1	ber of Units: Occupancy Percentage: 100			Percentage of interior (above grade) that is finished: 95					
Number of Parking Spac per owner	Spaces: 10 Number o 0		f Covered Parking Spaces: Perc 0		rcentage of Basement that is finished:				
Subject Unit Details (ch	eck all tl	nat apply)							
Exterior:	🗖 Brie	ck/Stone		Wood/Siding		Stucco	Concrete	Metal	Glass
Heating/Cooling:	L Ind Heating	ividual Units		Central Air ditioning	⊡ Heat	Central	Individual A/C Units	None None	
Interior Walls:	☑ Pa Drywall	inted		Wood/Paneling	D Brick	/Block	Concrete	Other	
Ceilings:	Pa Drywall	inted	•	Drop-in Tiles		Wood	Unfinished	D Metal	
Floors:	Carpet			Ceramic		Vinyl	Hardwood	Concrete	Other
Fire Sprinklers:	🗖 Yes	5	•	No					
Elevators:	☑ No	ne		One		Two	Three	More than three	
Overall Building Condition:	Exe	cellent		Good	•	Average	🔽 Fair	Poor	Not Applicable
Environmental Concerns Observed:	C Yes	5	~	No					

Notes/Comments:

Please note any interior or exterior deferred maintenance, neighborhood issues, needed repairs or hazardous conditions. Include any photographs that will help support issues reported.

Interior and exterior deferred maintenance/neighborhood Issues: Deferred Maintenance: Storage area, basement, gravel parking lot, awning. Deferred maintenance areas reportedly maintained by the town: sidewalk, and cracking cement at right of building (posted No Parking by the town). Neighborhood Issues: There are some areas of "paved vacant lots" and aging structures of the central business district buildings located west and south of the property. An active railroad operates down the street from the property (in photo of Diamond Street).

Hazards/Needed Repairs: Potential fire hazards in storage areas. Basement steps- no railing. The underside of the front awning is peeling paint. The basement shows evidence of recent water incursion/seepage from rain.

Inspection Photos



front





right



rear/back





main pharmacy/retail area



main pharmacy/retail area



main pharmacy/retail area



storage room: prep area



storage room



storage room



storage area- loft above two storage rooms



basement



basement: water seepage from rain (damp afterward)

awning (peeling paint hazard)



storage area hazard





sidewalk in front - trip/fall hazard (owner husband claimed maintained by town)



basement area showing water seepage area



cracked cement area next to right side of building (posted no parking)



street scene: diamond street, left of front of property, showing active railroad in neighborhood



street scene: diamond street, left of front of property



street scene: diamond street, right of the front of building



adjacent property: alleyway next to right side of property, taken from across diamond street, north side



adjacent property: directly north of property, across diamond street

adjacent property: northwest of property, across diamond street



adjacent property: vacant paved area across alleyway from front of property




adjacent property: northeast of property, across diamond street



adjacent property: insurance office building behind property to south of property parking area





© 2012 NVMS, Inc. All rights reserved